



Top Ten Reasons for Not Passing a STR Inspection

1. Bedroom windows do not meet egress requirements
2. Carbon Monoxide alarms not installed on all levels
3. E-911 number of building not posted or visible from road
4. Electrical panel legend (labeling) not provided
5. Stairs do not meet egress requirements; missing hand rails, low railing, etc.
6. Fire Extinguisher not mounted or accessible in kitchen
7. GFCI protected receptacles not functional or not installed in required locations
8. Interconnected Smoke Detectors not installed on all levels, in each bedroom and in high hazard areas
9. Service information for heating system not posted
10. 3-foot clear access to electrical panel not provided